Service Information

Mazda Motor Corporation





| Category B | Technical | | Ref. No. E002/15 <mark>A</mark> | Page 1 of 1 |
|--|-----------|--|------------------------------------|----------------|
| Coverage Distributor only Please inform your dealers | | | Date Issued January 14, 2015 | |
| Please convey this information to your □ Director ■ General Manager ■ Warranty Dept. ■ Parts Dept. ■ Training Dept. ■ Field Rep. | | | Date Revised April 9, 2015 | |
| Applicable Model | | Applicable Countries or Specifications | | |
| All models with SKYACTIV-Engine (Diesel and Gasoline) | | Worldwide | | |

REVISED


Revision NOTE: To prevent the oil pan from scratching by tool when tightening the drain plug, the hexagon head type drain plug has been changed to one with flange.

Subject: Introduction of Hexagon Head Type Drain Plug for Engine Oil Pan

DESCRIPTION

This Service Information introduces that the existing **hexagon head type** drain plug (LFE5-10-404) can be used for the oil pan of SKYACTIV-D&G engines. This drain plug and the originally equipped **hexagon socket head type** drain plug (FS50-21-249) are interchangeable in both ways.

*Either of the following two drain plugs can be used for SKYACTIV-D&G engine oil pan.



Tightening Torque (for both drain plugs) is: Refer to WORKSHOP MANUAL.

Ryu Shimizugawa Manager, Technical Information Gr. Technical Service Dept. Mazda Motor Corporation 2E40863123 (MC Internal Use)